

Photos

Photo 5.5.1 RN3 condition outside project site



Photo 5.5.2 Proposed access road alignment



Photo 5.5.3 Site access visibility (left)



Photo 5.5.4 Site access visibility (right)



Photo 5.5.5 RN3 between Yassa Village and Axe-Lourd Village



Photo 5.5.6 Intersection at Yassa Village



Photo 5.5.7 Commercial Frontage along RN3 through Axe-Lourd Village



Photo 5.5.8 Westbound on RN3 through Axe-Lourd Village



Photo 5.5.9 Airport Runway Overpass along RN3 exiting Douala



Photo 5.5.10 Dual-carriageway along Boulevard Beseke in Douala



Photo 5.5.11 Westbound on Bridge over Wouri River exiting Douala



Photo 5.5.12 Significant potholes at Bonaberi Market



Scott Wilson
www.scottwilson.com

KPDC
DIBAMBA POWER PROJECT ESIA

PHOTOS

Photo 5.5.13 RN3 between Bonaberi and Bekoko Interchange



Photo 5.5.14 Westbound on Bridge over Mungo River



Photo 5.5.15 Road tolls on RN3 between Mungo River and Tiko Town



Photo 5.5.16 Access to AES Sonel's powerplant at Limbe



Photo 5.7.1 From Location A



Photo 5.7.2 From Location B



KPDC
DIBAMBA POWER PROJECT ESIA

PHOTOS

Photo 5.7.3 Main Road by Yassa Junction.



Figure 5.7.4: From Location C



Figure 5.7.5 From Location D



Photo 5.7.6 Vegetation around residential receptor and view of soap factory from the road level



KPDC
DIBAMBA POWER PROJECT ESIA

PHOTOS

Photo 5.7.7 Vegetation around the closest residential receptor



Figure 5.9.1 *Pentadiplandra brazzeana*



Figure 5.9.2 *Rauvolfia vomitoria*



KPDC
DIBAMBA POWER PROJECT ESIA

PHOTOS