

**EMBRAER**  
**Table 1 - Corrective Action Plan**

| <b>Plant</b>                           | <b>Unit / Operation</b>               | <b>Parameters</b> | <b>Activity</b>                                                                                          | <b>Deadline</b> |
|----------------------------------------|---------------------------------------|-------------------|----------------------------------------------------------------------------------------------------------|-----------------|
| Faria Lima<br>Sao Jose dos Campos      | F-113<br>Paint Operations             | VOCs              | Substitution of high VOC primer epoxy by low VOC primer epoxy. If needed, install air pollution controls | April 2006      |
| Faria Lima<br>Sao Jose dos Campos      | F-113<br>Chemical Cleaning Operations | VOCs              | Substitution of solvent-based (perchloroethylene) material by non-solvent based material.                | August 2006     |
| Faria Lima<br>Sao Jose dos Campos      | F-210<br>Paint booth                  | VOCs              | Process improvements. If needed, install air pollution controls                                          | August 2006     |
| Eugenio de Melo<br>Sao Jose dos Campos | Paint Operations                      | VOCs              | Substitution of high VOC primer epoxy by low VOC primer epoxy. If needed, install air pollution controls | June 2006       |