

Corrective Action Plan.

Zhejiang Babei Necktie & Weaving Co. Ltd

November 29, 2004.

Item	Description	Completion Date
1	Review use of water and operation and maintenance of the effluent treatment systems at the office, weaving plant and dyeing plant	June 2005
2	If monitoring after completion of Item 1 shows that effluent concentrations of oil and grease or total suspended solids at any site exceed IFC guideline values, modify treatment systems to achieve compliance with IFC and local effluent quality requirements.	June 2006
3	Build secondary containment walls around generator oil storage tanks at all sites.	June 2005