

Environmental Action Plan

Altyn-Ajdar, IFC Reference 23593

February 28, 2005

Item	Description	Completion Date
1	Measure emissions of particulate matter, and oxides of sulfur and nitrogen from the boiler exhaust.	June 2005
2	If shown necessary by Item 1, reduce emission of these parameters to meet IFC and local requirements.	June 2006
3	Undertake an Occupational Health and Safety Audit of the factory.	June 2005
4	Implement corrective actions as shown necessary by the OHS audit, item 3.	June 2006